

### 3-wire connection

This is a method of connecting a single phase AC variable voltage control unit to a motor. It is recognised as giving the best performance. The capacitor is connected separately to the controller with three connections to the controller. The advantage over two-wire control is that the capacitor does not see the controlled waveform resulting in the motor operating cooler and more efficiently.

